








ASSEMBLE INSTRUCTION



A.x24  Φ3*12mm	B.x18  M6*70mm	C.x26  M6*100mm	D.x48  Φ10*13mm	E.x80  Φ8*30mm	F.x1  M4	G.x12  Φ7*50mm	H.x88  Φ4*30mm
J.x1 	K.x4 	L.x8  Φ3.5*16mm	M.x16 	N.x16 	P.x6 	Q.x6  M4*20mm	R.x10  M6*60mm
CL.x3 		CR.x3 		DL.x3 		DR.x3 	


PART LIST



Carton 1	8 9 10 18 21 23 24 28 29 30 33 A.B.C.D.E.F.G.H.J.K.L.M.N.P.Q.R
Carton 2	1 2 3 4 5 6 7 11 12 13 14 15 16 17 19 20 22 25 26 27 31 32 CL.CR.DL.DR.

01





B		6
D		6
E		6
F		1



x2

02


B		12
D		6
E		6
F		1



x2



03

C		8
D		8
E		4
F		1






04

H		30
J		1




05

J		1
K		4
L		8





06

R		2
D		2
E		2
F		1






07

C		8
D		8
E		16
F		1








08

R		4
D		4
E		4
F		1




09

C		2
D		2
E		10
F		1
J		1
M		4
N		4




10

C		8
D		8
E		16
F		1





11

H		18
J		1
P		3
Q		3



12






A		12
E		12
J		1
CL		3
CR		3



x3





13

R		4
D		4
E		4
F		1





14

G		12
F		1




15

A		12
J		1
H		12
M		12
N		12
P		3
Q		3
DL		3
DR		3



x3

16



17

H		28
J		1

